



IMPORTANT INFORMATION REGARDING USE OF CHERNE SMOKE PELLET PRODUCTS

APPLIES TO #1000000977

THESE PRODUCTS ARE INTENDED STRICTLY FOR USE BY TRAINED PROFESSIONALS.

Cherne Smoke Pellets should only be handled by individuals who are experienced in smoke testing applications and understand the safety and operational requirements associated with their use. Misuse may result in suboptimal performance, damage to surrounding areas, or pose health and safety risks to the user and others nearby.

USAGE:

- 1.) Use a fire-resistant surface or container.
- 2.) Ignite the flat, exposed edge of pellet with flame until smoking.

Please ensure you review all safety documentation, including the Safety Data Sheet (SDS), before using any smoke pellet products. If you need guidance on correct usage or suitability for your application, contact **Cherne Customer Service before purchase or deployment at 1-800-843-7584.**

USAGE GUIDELINES

Cherne Smoke Pellets are non-pyrotechnic and do not pose an explosion risk. However, they do produce dense smoke rapidly and should be used conservatively. Always start with the smallest effective amount and increase only as needed.

Approximate Smoke Output for 1000000977: ~850 cu. ft. in 60 seconds

Each pellet smokes for 60 seconds and covers 850 cubic feet. Group pellets for longer or higher-density output.

Typical use for leak detection or smoke detector testing is about one cubic foot of smoke per cubic foot of space. This may increase depending on system requirements. For airflow and draft visualization, a lighter smoke concentration is recommended to ensure visibility of patterns.

These figures are general guidelines; results may vary depending on the specific test environment. If you're unsure how to apply smoke effectively or safely for your application, please reach out to Cherne Customer Service for support.



SAFE USE, HANDLING AND DISPOSAL GUIDELINES

WARNINGS:

- For adult professional use only – keep away from children.
- Do not use near flammable materials. Avoid placing near open flames or ignition sources.
- Operate only in outdoor or well-ventilated areas or with appropriate respiratory protection.
- Do not hold in hand while igniting.
- Direct exposure to smoke may cause irritation to eyes, skin or respiratory tract. Avoid breathing in smoke.
- Ingestion may be harmful. Keep away from food and beverages.
- Always read product labeling and SDS thoroughly before use.

STORAGE:

Keep sealed in original container. Store in a dry, cool and well-ventilated area. Avoid direct sunlight and excessive moisture. Store out of reach of children.

DISPOSAL:

Smoke pellets are not classified as explosive. Disposal should comply with all applicable local regulations and may include incineration or general waste handling as appropriate.

For additional information or questions about the range of Cherne smoke testing solutions, visit our website or contact Cherne Customer Service.

Find us on



©2025 OateySCS. All Rights Reserved. This information is based on data believed to be reliable but Oatey makes no warranties, express or implied, as to its accuracy and assumes no liability arising out of its use. The data listed falls within the normal range of product properties but should not be used to establish specification limits or used alone as the basis of design. Oatey's liability to purchasers is expressly limited to the terms and conditions of sale. Oatey is a trademark of Oatey Co. Oatey Co. is part of the Oatey family of companies. All other trademarks can be found on www.oatey.com.